T.G. MILLER, P.C.

ENGINEERS AND SURVEYORS

605 W. State Street | Ithaca, NY 14850 | phone 607-272-6477 | fax 607-273-6322 | www.tgmillerpc.com

A site visit to the Renwick Brook Culvert Replacement Project site, located near the intersection of Cayuga Heights Road and Remington Road South, was conducted by T.G. Miller Personnel on June 10, 2026. The site visit assessed trees to be demolished for potential Northern Long Eared Bat habitat compatibility. A summary of the findings are shown in the Table below.

Tree #	Species	Size (in)	Bark Texture	Cavities	Notes
1	Basswood	34”	Ridged, no gaps	Confirmed	Splits into 17” and 12” stems.
2	Basswood	34”	Ridged, no gaps	Likely	Splits into 16” and 14” Stems.
3	Basswood	18”	Ridged, no gaps	Possible	
4	Hemlock	10”	Vertical Cracks, minor gaps	None	Tree is dead.
5	Hemlock	8”	Vertical Cracks, no gaps	Unlikely	
6	Tree of Heaven	12”	Smooth	Unlikely	
7	Sugar Maple	8”	Ridged, no gaps	Likely	
8	White Ash	10”	Ridged, no gaps	Possible	
9	Basswood	8”	Ridged, no gaps	None	
10	Basswood	14”	Ridged, minor gaps	Likely	

A Photo Log can be found in the following pages. Please see the attached Exhibit that shows the location of the trees. See the coordinates of key trees below.

Tree #	X Coordinate	Y Coordinate
1*	843468.82	900997.14
2*	843468.82	900997.14
3	843457.12	900995.94
7	843422.47	901001.44
8**	843409.83	901011.95
10	843514.92	843514.92

*Trees 1 and 2 are part of the same clump; this clump was shot once by survey.
** Tree not surveyed; location is approximate.

Tree #1

Tree #2

Tree #3



Tree #4

Tree #5

Tree #6



Tree #7

Tree #8

Tree #9

Tree #10